

ERT - Simulacro / ERT - Drill: Run on 22/05/2022

This document was created in MY Compliance Management on 08/06/2022 13:57:15

Audit Details	
Audit name:	ERT - Simulacro / ERT - Drill
Audit date:	22/05/2022
Auditor:	David Pinto
Audit details:	Simulacro en áreas de trabajo / Work Area Drill
Overall Outcome:	Completed
Emergencia / Emergency	Emergencias medicas o por lesion / Medical or injury emergencies
Breve descripción del evento / Brief Event Description	22 mayo 2022. Simulacro Presa Este, Derrame de hidrocarburo y colaborador que sufre caída de articulado. Articulado 740 sobre ruptura de una manguera hidraulica, dentro de las celdas 25-30 en la Presa Este de TMF, al momento del Operador intentar bajar para la contencion del derrame sufre caída desde la escalera provocandole lesion en pierna derecha. 22 May 2022. Simulated East Dam, Spill of hydrocarbon and collaborator suffering fall of articulated truck. Articulated truck 740 sobre rupture of a hydraulic hose, inside cells 25-30 in the East Dam of TMF, at the time of the Operator attempt to get down for containment of the spill suffers from fall from the ladder causing injury to his right leg.
Especificar ubicación / Specify Location	Presa Este TMF
Hora de inicio / Starting Time	10:14
Hora de finalización / Ending Time	11:05
Departamento / Department	TMF - Earthwork

Notes

22 de mayo 2022, Simulacro en Presa Este. Derrmae de hidrocarburo con colaborador que sufre caída produciendole golpe en Pierna derecha.

- Se produce retraso al ingreso por trabajos de Construcccion en la entrada al camino a la Presa Este, entre Bypass de B60 a plataforma 5.
- Mejorar el reconocimiento de las areas e identificación de los cuellos de botella por parte de ERT y clinica
- Mantener señalitica de las presas, celdas y plataformas

May 22, 2022, Drill in Presa Este. Spill of hydrocarbon with collaborator who suffers falling producing blow in right leg.

- The entrance is delayed due to construction work at the entrance to the East Dam, between Bypass B60 to platform 5.
- Improve area recognition and identification of bottlenecks by ERT and clinica
- Keep signs of dams, cells and platforms

Response Summary		
Section	Completed	Not completed
Audit	1	0

ERT - Simulacro / ERT - Drill: Run on 22/05/2022

This document was created in MY Compliance Management on 08/06/2022 13:57:15


Audit Criteria

#	Criteria	Details	Response
1	Completed Drill	Responsible will determine the drill	Completed

Signatures

Capacity: supervisor

Name: David Pinto



Documents



ingreso a ambulancia



ambulancia



traslado de celda a ambulancia



atencion de paciente en sitio



22b1bb83-e81a-4527-9866-2f2577abad57.jpg

PDF - Simulacro Presa Este TMF.pdf

DOC - Drill Plan Guidance Form 2022 Derrame TMF.DOC